SEPA Environmental Event Report

ENV/0898937 **Notification Number Elms Event Number** 1

Event Description odour - 2 Sisters - Coupar Angus

Reported By

Origin Complainant Surname

Forename Affected Medium Air

Organisation **Investigating Team** Falkirk, Alloa, Stirling and Perth Name

Address 1 **Investigating Officer**

Address 2 Address 3

Town

Post Code Tel No

Fax No

Email Address

Receiving Officer

Time Received 17:12:00 **Date Received**

20-MAY-19

17:25:00 Time Responded

Date Responded 20-MAY-19

Within 24? Yes

Location Scotmid Car Park, George St, Coupar Angus **Located Notifiers Address?**

Date Event Occurred 20-MAY-19

Site Name 2 Sisters Poultry Limited, Coupar Angus **RSA Site?** No

Catchment

Mental H&S Low

Assessment

Assessment Description

Impact Category 3 - Minor Type Odour

Cause Structural Failure Sector Industry IPC / PPC part A **Sepa Activity** Source PPC

Farm Name **Potential Hazard**

Complainants Notified? Yes **Details**

SEPA Environmental Event Report

Action Description

Standby Officer contacted factory at 17.40Hrs to pass on details of complaint.

approx. 07:30hrs 21/05/2019: contacted the site with details of the odour notification for to investigate: noticed odour outside Scotmid, very close to factory. Sulphur smell - generally horrible. Very hard to describe 4 out of 5. little wind, dry and mild.

responded initially at 07:36 to advise would investigate and be back in touch. 11:13 MW: "I have investigated the Pollution complaint reported to SEPA at 17:12:41 20/05/2019.

Unfortunately I would agree the complaint arose as the site was trying unblock an external sew age drain, which had caused the male toilet block to back up. The site handyman was called in to unblock the drain, which although successful allowed polluted air to escape the site boundary. I can confirm the sew age drain was cleared without difficulty and is working correctly"

13:39 emailed (as requested) and advised that SEPA believe the source of the odour in this instance was due to the unblocking of sew age from a blocked sew er on site.

NFA at present. Complaint received out of hours so unsubstantiated by SEPA officer. We believe the souce of the odour was identified (sewage from blocked sewer on site) this problem has been resolved. long-term SEPA are working continually to examine environmental performance at the site and in particular to address the complex issue of odour management.